

Sale Name: (2) 2009 FREIGHTLINER B2 THOMAS SAF-T-LINER C2 SCHOOL BUSES
Located in INWOOD, NY

LOT ICCNY092702 - 2009 FREIGHTLINER B2 THOMAS SAF-T-LINER C2 SCHOOL BUS #658



VIN 4UZABRDJ19CZ82702

Description

LOCATED IN INWOOD, NY
DEADLINE to PICKUP is FEBRUARY 8, 2023

POSSIBLE



YEAR BY VIN: 2009
YEAR BY TITLE: 2009

FREIGHTLINER B2 THOMAS SAF-T-LINER C2 SCHOOL BUS #658

VIN: 4UZABRDJ19CZ82702
Titled As: 2009 THOMA B2B
MILES: 113,931
SEAT PAX: 65 Passengers with LAP Seat Belts

SPECS:

- **6 Cylinder, 7.2L (439 CID) Mercedes Benz 388 MBE900 Diesel Conventional Nose Front Engine**
- **Air Brakes**
- **Automatic Transmission**
- **Rear Air Suspension**
- 11 Passenger Windows in Length
- Date of Manufacture 10/2007
- Date of Body Assembly 10/2007
- Originally Built for NY State Requirements
- GVWR: 31,000 LBS
- GAWR Front: 10,000 LBS
- GAWR Back: 21,000 LBS

FEATURES:

- **Front and Rear Air Conditioning**
- Air Passenger Door
- Tinted Windows
- White Roof
- Dual Rear Wheels

SAFETY:

- Lap Seat Belts
- 4 Emergency Exit Windows
- 2 Emergency Roof Hatches
- Side Emergency Door

FUNCTIONALITY TESTS:

- Bus Starts
- Bus Drives Forward
- Bus Drives Backward
- Brake Pedal Functions
- **New Batteries ARE SUGGESTED for Pickup**

CONDITION:

- DATE REMOVED FROM SERVICE 06/2022
 - **Inspection Expiration Date 02/2023**
 - **CHECK ENGINE Light is ON**
 - **ABS Light is ON**
 - **CHECK TRANSMISSION Light is ON**
 - **Transmission Is In Limp Mode**
 - Scrapes on the Driver Side Rear Panel and Corner
 - Paint Fade
 - Lower Window In Rear Emergency Door is Broken
 - Paint Wear on Passenger Side Rear Panel
 - Undercarriage Surface Rust
 - **NAME, RADIOS, AND PA SYSTEMS MAY BE REMOVED**
 - Clean Title
 - LOCATED IN INWOOD, NY
- Please See Photos And Pickup Details

THIS ITEM HAS A RESERVE

Quantity: 1



<https://bid.422sales.com/>